

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave.St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:**Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-006020**Date Inspected:** 01-Apr-2009**Project Name:** SAS Superstructure**OSM Arrival Time:** 645**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1845**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Zhao Chen Sun**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG components**Summary of Items Observed:**

On the date CALTRANS OSM Quality Assurance (QA) Inspector, Dilip Chakrabarti was present during the times noted above for observations relative to the work being performed.

Bay# 6-OBG Assembly

This QA Inspector randomly observed the following work in progress:

Magnetic Particle Testing:

For Green Tag:

This QA inspector performed Magnetic Particle Testing (MT) of approximately 15% of the area previously tested and accepted by ZPMC Quality Control personnel. This QA Inspector generated a TL-6028 MT report on this date.

The member and the weld designations are as follows:

Sl # Section # Weld # Green Tag # Location

1. BP 188-001 012,014,016,018 006066 11CE

2. SP 786-001 017,019,021,023 006065 11 EW

3. SP 113-001 015,016,017,018 005559 11 AW

4. SP 560-001 015,016,017,018 005556 11 EE

5. DP 205-008 001,002 005555 7 D

6 DP 204-008 001,002 005554 7 D

Bay# 6-Tower Assembly:

This QA Inspector randomly observed the following work in progress:

WELDING INSPECTION REPORT

(Continued Page 2 of 3)

FCAW Process:

Welding of weld joint# 4 located on PCMK WD1 CBSA3-1-5. Welder is identified as 053609. ZPMC QC is identified as Zhang Bao Bo. The welding variables recorded by QC appeared to comply with the specified WPS no. B-T-2332-TC-P4-F-1.

Welding of weld joint# 1 located on PCMK WD1 CBSA3-1-5. Welder is identified as 058174. ZPMC QC is identified as Zhang Bao Bo. The welding variables recorded by QC appeared to comply with the specified WPS no. B-T-2332-TC-P4-F-1.

Welding of weld joint# 4 located on PCMK WD1 CBSA3-1-7. Welder is identified as 053609. ZPMC QC is identified as Zhang Bao Bo. The welding variables recorded by QC appeared to comply with the specified WPS no. B-T-2332-TC-P4-F-1.

Welding of weld joint# 1 located on PCMK WD1 CBSA3-1-7. Welder is identified as 08174. ZPMC QC is identified as Zhang Bao Bo. The welding variables recorded by QC appeared to comply with the specified WPS no. B-T-2332-TC-P4-F-1.

Bay # 7-OBG Assembly:

This QA Inspector randomly observed the following work in progress:

Ultrasonic Testing:

This QA inspector performed Ultrasonic Testing (UT) of approximately 10% of the area previously tested and accepted by ZPMC Quality Control personnel. This QA Inspector generated a TL-6027 UT report on this date.

The member and the weld designations are as follows:

Sl # Section # Weld # Green Tag # Location

1. SP 597-001 047,049 NA NA
2. SP 637-001 047,049 NA NA
3. SP 783-001 043,045 NA NA
4. SP 743-001 051,053 NA NA
5. SP 505-001 056,058 NA NA
6. SP 557-001 052,054 NA NA

FCAW Process:

Welding of weld joints# 15&16 located on PCMK SP 142-001. Welder is identified as 202841. ZPMC QC is identified as Zhong Chong Biao. The welding variables recorded by QC appeared to comply with the specified WPS no. B-T-2132- 3.

Welding of weld joints# 19&20 located on PCMK SP 142-001. Welder is identified as 051246. ZPMC QC is identified as Zhong Chong Biao. The welding variables recorded by QC appeared to comply with the specified WPS no. B-T-2132- 3.

Welding of weld joints# 23&24 located on PCMK SP 142-001. Welder is identified as 053742. ZPMC QC is identified as Zhong Chong Biao. The welding variables recorded by QC appeared to comply with the specified WPS no. B-T-2132- 3.

WELDING INSPECTION REPORT

(Continued Page 3 of 3)

Unless otherwise noted, all work observed on this date appeared to be generally comply with applicable contract document

Summary of Conversations:

No relevant conversations.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang 150-0042-2372, who represents the Office of Structural Materials for your project.

Inspected By:	Chakrabarti,Dilip Kumar	Quality Assurance Inspector
Reviewed By:	Clifford,William	QA Reviewer
